



Phone: +44(0) 1784 818181
Email: sales@phl.co.uk
Website: https://www.phl.co.uk

Specification

| | |
|----------------|---------|
| Stock No | 557410 |
| Type | REACH |
| Make | TOYOTA |
| Model | RR B3 |
| Year | 2008 |
| Euromast | 3F950 |
| Hours | 0 |
| Capacity | 1600 kg |
| Lift height | 9500 |
| Values | |
| Quality Rating | 3 |

Mechanical

| | |
|---------------------------------|----------------|
| Character. | |
| Load Centre (c) | 400/500/600 mm |
| Operating mode (Characteristic) | Seated |

| | |
|--------------------------------|---------|
| Weights | |
| Service weight (Total weight) | 4000 kg |

| | |
|------------|--------------|
| Wheels | |
| Tyres type | Polyurethane |

| | |
|---------------------------------------|----------------|
| Dimensions | |
| Free lift (h2) | 3200 mm |
| Lift height (h3) | 9500 mm |
| Extended height (h4) | 10500 mm |
| Height of overhead guard (cabin) (h6) | 2160 mm |
| Height of reach legs (h8) | 320 mm |
| Overall length (l1) | 2250 mm |
| Length to fork face (l2) | 1250 mm |
| Overall width (b1/b2) | 1280 mm |
| Forks length (l) | 1000 mm |
| Fork carriage (class) | DIN 15173 / 2A |
| Fork carriage width (b3) | 900 mm |
| Width between legs (b4) | 900 mm |
| Length of chasis (l7) | 1775 mm |
| Collapsed height (h1) | 3875 mm |
| Forks height (s) | 40 mm |
| Forks width (e) | 100 mm |

| | |
|---------------|-----------------|
| Performance | |
| Service brake | electromagnetic |

| | |
|--------------------------|------------------|
| Drive | |
| Battery class | British Standard |
| Battery voltage/capacity | 48V / 775Ah V/Ah |

| | |
|-----------------------------------|----------------------|
| Attachment | |
| Attachments (Has attachment) | Sideshift and Forks. |
| Attachment type (Attachment type) | Sideshifts |

| | |
|---------------------------|----------|
| Engine | |
| Engine type (Engine type) | electric |

Opinion

Location

| | |
|-------------|------------------------|
| Extras | |
| Extras | SS, Mesh Screen Guard. |
| Extras Hyds | 3rd & 4th |

Visual



Appearance: Scruffy

Mechanical Status: Not tested

More: [Click here for more photos](#)

