

## Specification

|                |          |
|----------------|----------|
| Stock No       | 311673   |
| Type           | PALLET   |
| Make           | LINDE    |
| Model          | T20S 144 |
| Year           | 2004     |
| Euromast       | 1150X520 |
| Hours          | 5674     |
| Capacity       | 2000 kg  |
| Lift height    | 200      |
| Values         |          |
| Quality Rating | 3        |

## Mechanical

|                                 |          |
|---------------------------------|----------|
| Character.                      |          |
| Load Centre (c)                 | 500 mm   |
| Operating mode (Characteristic) | Stand-on |

## Weights

|                                |        |
|--------------------------------|--------|
| Service weight (Total weight ) | 890 kg |
|--------------------------------|--------|

## Wheels

|                       |              |
|-----------------------|--------------|
| Tyres type            | Polyurethane |
| Tyres front condition | 85%          |
| Tyres rear condition  | 75%          |

## Dimensions

|                            |         |
|----------------------------|---------|
| Lift height (h3)           | 200 mm  |
| Overall length (l1)        | 1950 mm |
| Length to fork face (l2)   | 800 mm  |
| Overall width (b1/b2)      | 790 mm  |
| Forks length (l)           | 1150 mm |
| Fork spread (min/max) (b5) | 520 mm  |
| Width between legs (b4)    | 195 mm  |
| Collapsed height (h1)      | 1400 mm |

## Performance

|               |                 |
|---------------|-----------------|
| Service brake | electromagnetic |
|---------------|-----------------|

## Drive

|                          |                |
|--------------------------|----------------|
| Battery voltage/capacity | 24V/345Ah V/Ah |
| Battery (Acc. to DIN)    | WB             |

## Engine

|                           |          |
|---------------------------|----------|
| Engine type (Engine type) | electric |
|---------------------------|----------|

## Opinion

## Extras

|        |          |
|--------|----------|
| Extras | 1150x520 |
|--------|----------|

## Visual



**Appearance:** Very good visual appearance for age, seat ripped a bit,

**Mechanical Status:** Good Mechanical Condition

**More:** [Click here for more photos](#)

