



Phone: +44(0) 1784 818181

Email: sales@phl.co.uk

Website: https://www.phl.co.uk

Specification	
Stock No	352907
Type	REACH
Make	LINDE
Model	R14HD 115
Year	2004
Euromast	3F920
Hours	16432
Capacity	1400 kg
Lift height	9200
Values	
Quality Rating	3
Mechanical	
Character.	
Load Centre (c)	600/500 mm
Operating mode (Characteristic)	Seated
Wheelbase (y)	1275 mm
Load distance (x)	311 mm
Weights	
Service weight (Total weight )	3620 kg
Axle load with load (front/rear)	1800/1090 kg
Wheels	
Tyres type	Polyurethane
Tyre size front	285 x 100 mm
Tyre size rear	343 x135 mm
Track width rear (b11)	1150 mm
Wheels (front/rear (x=driven))	1x/2
Dimensions	
Mast or fork carriage tilt (alpha,beta)	2/4 grad
Free lift (h2)	3080 mm
Lift height (h3)	9200 mm
Height of overhead guard (cabin) (h6)	2110 mm
Height of reach legs (h8)	310 mm
Overall length (l1)	2384 mm
Length to fork face (l2)	1184 mm
Overall width (b1/b2)	1250 mm
Forks length (l)	1000 mm
Fork carriage (class)	DIN 15173 / 2A
Fork carriage width (b3)	830 mm
Fork spread (min/max) (b5)	296/690 mm
Width between legs (b4)	922 mm
Reach travel (l4)	496 mm
Ground clearance, mast (m1)	75 mm
Ground clearance, centre of wheelbase (m2)	75 mm
Turning radius (Wa)	1540 mm
Length of chasis (l7)	1638 mm
Ast across 1000x1200 (Ast)	2655 mm
Ast along 800x1200 (Ast)	2715 mm
Collapsed height (h1)	3950 mm
Seat/stand height (h7)	940/1030 mm
Forks height (s)	40 mm
Forks width (e)	80 mm
Performance	
Travel speed (With, w/o load)	13.5/13.5 km/h
Lifting speed (With, w/o load)	0.34/0.6 m/s
Lowering speed (With, w/o load)	0.55/0.45 m/s
Climbing ability (30 min rating - with, w/o load)	4.5/8.2 %
Maximum climbing (With, w/o load)	10/10 %
Acceleration time (With, w/o load)	5.5/4.8 sec
Service brake	hydraulic/electric
Drive	
Drive motor (60 min rating)	6 kW
Lift motor (15% rating)	12 kW
Battery class	IEC 254-2
Battery voltage/capacity	48V V/Ah
Other	
Noise level	63 dB
Working pressure	200 bar
Oil flow (For attachments)	6.5 l/min
Engine	
Engine type (Engine type)	electric
Opinion	
Extras	
Extras	SS,
Visual	



**Appearance:** Average Appearance for age.Seat ripped

**Mechanical Status:** Good operating condition.

**More:** [Click here for more photos](#)

