



Phone: +44(0) 1784 818181
Email: sales@phl.co.uk
Website: https://www.phl.co.uk

Specification

| | |
|----------------|-------------|
| Stock No | 330927 |
| Type | GAS |
| Make | LINDE |
| Model | H20T-01 391 |
| Year | 2016 |
| Euromast | 2W465 |
| Hours | 8436 |
| Capacity | 2000 kg |
| Lift height | 4650 |
| Values | 3 |
| Quality Rating | 4 |

Mechanical

| | |
|---------------------------------|--------|
| Character. | |
| Load Centre (c) | 500 mm |
| Operating mode (Characteristic) | Seated |

| | |
|--------------------------------|---------|
| Weights | |
| Service weight (Total weight) | 3395 kg |

| | |
|-----------------------|--------------|
| Wheels | |
| Tyres type | Superelastic |
| Tyres front condition | WORN |
| Tyres rear condition | WORN |

| | |
|---------------------------------------|----------------|
| Dimensions | |
| Lift height (h3) | 4650 mm |
| Extended height (h4) | 5660 mm |
| Height of overhead guard (cabin) (h6) | 2100 mm |
| Overall length (l1) | 3600 mm |
| Length to fork face (l2) | 2300 mm |
| Overall width (b1/b2) | 1150 mm |
| Forks length (l) | 1250 mm |
| Fork carriage (class) | DIN 15173 / 2A |
| Fork carriage width (b3) | 1000 mm |
| Length of chasis (l7) | 2200 mm |
| Collapsed height (h1) | 2870 mm |
| Forks height (s) | 550 mm |
| Forks width (e) | 900 mm |

| | |
|---------------|-------------|
| Performance | |
| Service brake | hydrostatic |

| | |
|-----------------------------|----------|
| Drive | |
| Drive motor (60 min rating) | 28 kW |
| Battery voltage/capacity | 12V V/Ah |

| | |
|-----------------------------------|------------|
| Attachment | |
| Attachment type (Attachment type) | Sideshifts |

| | |
|-------------------------------|------------|
| Engine | |
| Engine rated power (ISO 1585) | 28 kW |
| Cylinders/Displac. ccm | 4 cylinder |
| Engine type (Engine type) | gas |

Opinion

Location

| | |
|-------------|------------------------------------|
| Extras | |
| Extras | SS, HALF CAB, FLEXI DOORS, LIGHTS. |
| Extras Hyds | 3rd |

Visual



Appearance: Very good visual appearance with tidy interior. Seat ripped slightly.

Mechanical Status: Very good working order

More: [Click here for more photos](#)

