



Phone:
Email:
Website:

+44(0) 1784 818181
sales@phl.co.uk
https://www.phl.co.uk

Specification		
Stock No		321175
Type		DIESEL
Make	LINDE	
Model		H25D 393
Year		2009
Euromast		2W330
Hours		13590
Capacity		2500 kg
Lift height		3300
Values		
Quality Rating		3
Mechanical		
Character.		
Load Centre (c)		500 mm
Operating mode (Characteristic)		Seated
Wheelbase (y)		1905 mm
Weights		
Service weight (Total weight)		4275 kg
Axle load without load (front/rear)		1930/1940 kg
Axle load with load (front/rear)		5670/700 kg
Wheels		
Tyres type		Superelastic
Tyres front condition		80%Chipped
Tyres rear condition		75%Chipped
Tyre size front		27X10-12 mm
Tyre size rear		23X9-10 mm
Track width front (b10)		1008 mm
Track width rear (b11)		932 mm
Dimensions		
Mast or fork carriage tilt (alpha,beta)		5/8 grad
Lift height (h3)		3300 mm
Height of overhead guard (cabin) (h6)		2210 mm
Overall length (l1)		3750 mm
Length to fork face (l2)		2750 mm
Overall width (b1/b2)		1256 mm
Forks length (l)		1000 mm
Fork carriage (class)		DIN 15173 / 2A
Fork carriage width (b3)		1150 mm
Ground clearance, mast (m1)		119 mm
Ground clearance, centre of wheelbase (m2)		173 mm
Turning radius (Wa)		2420 mm
Ast across 1000x1200 (Ast)		4065 mm
Ast along 800x1200 (Ast)		4265 mm
Towing coupling height (h10)		698 mm
Collapsed height (h1)		2350 mm
Seat/stand height (h7)		1105 mm
Performance		
Travel speed (With, w/o load)		22 km/h
Lifting speed (With, w/o load)		0.47/0.48 m/s
Lowering speed (With, w/o load)		0.52/0.54 m/s
Climbing ability (30 min rating - with, w/o load)		32/33 %
Acceleration time (With, w/o load)		5.6/4.8 sec
Service brake		hydrostatic
Drive		
Battery voltage/capacity		12V V/Ah
Other		
Noise level		76 dB
Working pressure		170 bar
Oil flow (For attachments)		32 l/min
Traction control		HYDROSTATIC TRANSMISSION
Engine		
Manufacturer of engine/type		VW/BEU
Engine rated power (ISO 1585)		43 kW
Rated rpm		2600 rpm
Cylinders/Displac. ccm		4/1896
Fuel consumption (VDI)		2.5/3.2 l/h
Engine type (Engine type)		diesel
Opinion		
Extras		
Extras		NEW TYRES,SS,POSITIONER,LIGHTS,HALF CAB,



Appearance: Average appearance for the year. Seat pad worn,

Mechanical Status: Average condition.

More: [Click here for more photos](#)

