

Stock No 336933 GAS Туре Make LINDE Model H18T 350 Year 1999 Euromast 2F350 Hours 9752 Capacity 1800 kg Lift height 3500 Values Quality Rating 0

## Mechanical

Character. Load Centre (c)

500 mm Operating mode (Characteristic) Seated Wheelbase (y) 1500 mm

Weights

Service weight (Total weight ) 2910 kg 1250/1640 kg 4070/620 kg Axle load without load (front/rear) Axle load with load (front/rear)

Wheels

Tyres type Superelastic Tyres front condition 20% Tyres rear condition WORN Tyre size front 200/50-10 mm 18X7-8 mm Tyre size rear Track width front (b10) 945 mm Track width rear (b11) 873 mm

Dimensions Mast or fork carrage tilt (alpha,beta) 6/10 grad 3500 mm Lift height (h3) Extended height (h4) 4500 mm Height of overhead guard (cabin) (h6) 2070 mm Overall length (I1) 3460 mm Length to fork face (I2) 2260 mm Overall width (b1/b2) 1168 mm Forks length (I) 1200 mm DIN 15173 / 2A Fork carriage (class) Fork carriage width (b3) 1040 mm Ground clearance, mast (m1) Ground clearance, centre of wheelbase (m2) 98 mm 119 mm Turning radius (Wa) 2026 mm Ast across 1000x1200 (Ast) 3606 mm Ast along 800x1200 (Ast) 3806 mm Towing coupling height (h10) Collapsed height (h1) 560 mm 2080 mm Seat/stand height (h7) 1000 mm Forks height (s) Forks width (e) 40 mm 100 mm

Performance

Travel speed (With, w/o load) 18/18.5 km/h Lifting speed (With, w/o load) 0.57/0.58 m/s Lowering speed (With, w/o load) 0.53/0.45 m/s Climbing ability (30 min rating -with, w/o load) Acceleration time (With, w/o load) 31/26 % 4.9/4.4 sec Service brake hydrostatic

Drive

Drive motor (60 min rating) 27 kW Battery voltage/capacity 12V V/Ah

Other

76 dB Noise level Working pressure 230 bar Oil flow (For attachments) 18 l/min HYDROSTATIC TRANSMISSION Traction control

Attachment

Attachments (Has attachment) Sideshift and Forks. Attachment type (Attachment type) Sideshifts

Engine

Manufacturer of engine/type VW/ADF Engine rated power (ISO 1585) 27 kW Rated rpm 2300 rpm Cylinders/Displac. ccm 4/1781 Fuel consumption (VDI) 2.3 l/h Engine type (Engine type) gas

Opinion

Location

Extras Extras Extras Hyds

SS, Lights



Appearance: Average appearance for the year.

Mechanical Status: Good working condition

More: Click here for more photos







