

Specification

| | |
|----------------|----------|
| Stock No | 341024 |
| Type | ELECTRIC |
| Make | LINDE |
| Model | E20-01 |
| Year | 2017 |
| Euromast | 3F476 |
| Hours | 3285 |
| Capacity | 2000 kg |
| Lift height | 4760 |
| Values | 3 |
| Quality Rating | 3 |

Mechanical

| | |
|---------------------------------|--------|
| Character. | |
| Load Centre (c) | 500 mm |
| Operating mode (Characteristic) | Seated |

Weights

| | |
|--------------------------------|---------|
| Service weight (Total weight) | 4250 kg |
|--------------------------------|---------|

Wheels

| | |
|-----------------------|--------------|
| Tyres type | Superelastic |
| Tyres front condition | Worn |
| Tyres rear condition | Worn |

Dimensions

| | |
|---------------------------------------|----------------|
| Lift height (h3) | 4760 mm |
| Extended height (h4) | 5800 mm |
| Height of overhead guard (cabin) (h6) | 2060 mm |
| Overall length (l1) | 3650 mm |
| Length to fork face (l2) | 2450 mm |
| Overall width (b1/b2) | 1150 mm |
| Forks length (l) | 1200 mm |
| Fork carriage (class) | DIN 15173 / 2A |
| Fork carriage width (b3) | 1100 mm |
| Length of chasis (l7) | 2200 mm |
| Collapsed height (h1) | 2160 mm |
| Forks height (s) | 45 mm |
| Forks width (e) | 80 mm |

Performance

| | |
|---------------|-----------------|
| Service brake | electromagnetic |
|---------------|-----------------|

Drive

| | |
|-----------------------------|----------------|
| Drive motor (60 min rating) | 2 x 9 kW |
| Battery voltage/capacity | 80 / 5002 V/Ah |

Attachment

| | |
|-----------------------------------|------------|
| Attachment type (Attachment type) | Sideshifts |
|-----------------------------------|------------|

Engine

| | |
|---------------------------|----------|
| Engine type (Engine type) | electric |
|---------------------------|----------|

Opinion

Location

Extras

| | |
|-------------|---------|
| Extras | SS, LED |
| Extras Hyds | 3rd |

Visual

Battery

| | |
|--|------|
| Battery Year (Battery Year of Manufacture) | 2017 |
|--|------|



Appearance: Poor Cosmetics

Mechanical Status: Good working condition

More: [Click here for more photos](#)

