

Specification

| | |
|----------------|---------------|
| Stock No | 341320 |
| Type | ELECTRIC |
| Make | LINDE |
| Model | E25-01 RENTAL |
| Year | 2017 |
| Euromast | 2W313 |
| Hours | 3216 |
| Capacity | 2500 kg |
| Lift height | 3150 |
| Values | 3 |
| Quality Rating | 0 |

Mechanical

| | |
|---------------------------------|--------|
| Character. | |
| Load Centre (c) | 500 mm |
| Operating mode (Characteristic) | Seated |

Weights

| | |
|--------------------------------|---------|
| Service weight (Total weight) | 4582 kg |
|--------------------------------|---------|

Wheels

| | |
|-----------------------|---------|
| Tyres type | Cushion |
| Tyres front condition | Good |
| Tyres rear condition | Good |

Dimensions

| | |
|---------------------------------------|----------------|
| Lift height (h3) | 3150 mm |
| Extended height (h4) | 4100 mm |
| Height of overhead guard (cabin) (h6) | 2070 mm |
| Overall length (l1) | 3400 mm |
| Length to fork face (l2) | 2300 mm |
| Overall width (b1/b2) | 1150 mm |
| Forks length (l) | 1100 mm |
| Fork carriage (class) | DIN 15173 / 2A |
| Fork carriage width (b3) | 1150 mm |
| Collapsed height (h1) | 2170 mm |
| Forks height (s) | 40 mm |
| Forks width (e) | 100 mm |

Performance

| | |
|---------------|-----------------|
| Service brake | electromagnetic |
|---------------|-----------------|

Drive

| | |
|--------------------------|---------------|
| Battery weight | 1202 kg |
| Battery voltage/capacity | 80 / 460 V/Ah |

Attachment

| | |
|-----------------------------------|------------|
| Attachment type (Attachment type) | Sideshifts |
|-----------------------------------|------------|

Engine

| | |
|---------------------------|----------|
| Engine type (Engine type) | electric |
|---------------------------|----------|

Opinion

Location

Extras

| | |
|-------------|-------------------|
| Extras | SS, LED, Half Cab |
| Extras Hyds | 3rd |

Visual

Battery

| | |
|--|-------|
| Battery Serial No | 10040 |
| Battery Year (Battery Year of Manufacture) | 2017 |

Docs

| | |
|--------------------------|---|
| TE (Through Examination) | 1 |
|--------------------------|---|



Appearance: Good Appearance for age.

Mechanical Status: Good working condition

More: [Click here for more photos](#)

