



Phone:
Email:
Website:

+44(0) 1784 818181
sales@phl.co.uk
https://www.phl.co.uk

Specification

Stock No	327094
Type	DIESEL
Make	LINDE
Model	H30D-01 393 HIGH CAB
Year	2012
Euromast	2W395
Hours	10559
Capacity	3000 kg
Lift height	3950
Values	3
Quality Rating	4

Mechanical

Character.	
Load Centre (c)	500 mm
Operating mode (Characteristic)	Seated
Wheelbase (y)	1930 mm

Weights	
Service weight (Total weight)	4735 kg
Axle load without load (front/rear)	1950/2270 kg
Axle load with load (front/rear)	6420/800 kg

Wheels	
Tyres type	Superelastic
Tyres front condition	55%
Tyres rear condition	70%
Tyre size front	27X10-12 mm
Tyre size rear	23X9-10 mm
Track width front (b10)	1008 mm
Track width rear (b11)	932 mm

Dimensions	
Mast or fork carriage tilt (alpha,beta)	5/8 grad
Lift height (h3)	3950 mm
Height of overhead guard (cabin) (h6)	2650 mm
Overall length (l1)	3600 mm
Length to fork face (l2)	2800 mm
Overall width (b1/b2)	1256 mm
Forks length (l)	800 mm
Fork carriage (class)	DIN 15173 / 3A
Fork carriage width (b3)	1150 mm
Ground clearance, mast (m1)	119 mm
Ground clearance, centre of wheelbase (m2)	173 mm
Turning radius (Wa)	2444 mm
Ast across 1000x1200 (Ast)	4089 mm
Ast along 800x1200 (Ast)	4289 mm
Towing coupling height (h10)	698 mm
Collapsed height (h1)	2650 mm
Seat/stand height (h7)	1105 mm

Performance	
Travel speed (With, w/o load)	22 km/h
Lifting speed (With, w/o load)	0.47/0.48 m/s
Lowering speed (With, w/o load)	0.52/0.54 m/s
Climbing ability (30 min rating - with, w/o load)	27/30 %
Acceleration time (With, w/o load)	5.7/4.9 sec
Service brake	hydrostatic

Drive	
Battery voltage/capacity	12v V/Ah

Other	
Noise level	79 dB
Working pressure	170 bar
Oil flow (For attachments)	32 l/min
Traction control	HYDROSTATIC TRANSMISSION

Engine	
Manufacturer of engine/type	VOLKSWAGEN
Rated rpm	2600 rpm
Cylinders/Displac. ccm	4Cylinders
Engine type (Engine type)	diesel

Opinion

Extras	SS,FULL
Extras	CAB,LIGHTS,HEATER,WINDSCREEN WIPERS ALL OVER,REAR GLASS HEATED,

Visual



Appearance: Good Appearance for age.

Mechanical Status: Good working condition

More: [Click here for more photos](#)

